



KD/RTA fittings cannot be added to the center back edge of the Top because the end insets are too large, causing the KD/RTA fittings to overlap. Please rectify this issue in the Construction Parameters dialog.

OK